

# Site Visit Report



100 Grove Street  
Worcester, MA 01605  
T 508-856-0321  
F 508-856-0357  
gravesengineering.com

<b>Date:</b>	November 4, 2022	<b>Prepared By:</b>	Olivia Caton
<b>Client:</b>	Sutton Planning Board	<b>Arrived on site:</b>	2:50 PM
<b>Project:</b>	Unified Parkway	<b>Left site:</b>	3:50 PM
<b>Contractor:</b>	Walsh Contracting Corp.	<b>Site Conditions:</b>	Dry
<b>Contractor Contact:</b>	John Walsh	<b>Weather:</b>	65°, Clear

## Transmitted by:

<input checked="" type="checkbox"/> Mail	<input checked="" type="checkbox"/> E-mail
<input type="checkbox"/> Hand	<input type="checkbox"/> Other:
<input type="checkbox"/> Fax	

## Comments:

Graves Engineering, Inc. (GEI) was on-site to observe construction of the road's drainage/stormwater management system. This site visit was conducted throughout the entire site. I observed the following:

### General Site:

- The contractor was performing utility work in Providence Road.
- The uppermost portion of the slope between stations 8+00 and 9+00 needs to be reseeded.
- The area with jute matting between stations 8+00 and 9+00 was beginning to experience grass growth.
- The contractor was moving earth material and hydroseeding slopes on the lots between stations 32+00 and 42+00.

### Stormwater Management Areas:

- Stormwater Management Area (SWMA) #1 was experiencing sparse grass growth.
- The jute matting near Forebay 2B in SWMA #2 was well-maintained.
- Grass growth had not yet occurred in SWMA #2 and SWMA #3 near the emergency spillways.

Based upon visual observations only, the work observed today appeared to be consistent with the approved plans.

## Action to be Taken:

Client will be notified of this site visit by way of this report.

## Copies:

cc: John Walsh; Walsh Contracting Corp.  
Matthew Piekarski; The Kraft Group, LLC

## Photos:

The following photos were taken during today's site visit.



**Photo 1:** The contractor was performing utility work in Providence Road.



**Photo 2:** The uppermost portion of the slope between stations 8+00 and 9+00 needs to be reseeded.





**Photo 3:** The area with jute matting between stations 8+00 and 9+00 was beginning to experience grass growth.