Site Visit Report



100 Grove Street Worcester, MA 01605 T 508-856-0321 F 508-856-0357 gravesengineering.com

Olivia Catan

Dranarad Dv. Date: November 11, 2022 Client: Sutton Planning Board Project: **Unified Parkway Contractor:** Walsh Contracting Corp.

Contractor Contact: John Walsh

| riepaieu by. | Olivia Catori |
|------------------|---------------|
| Arrived on site: | 2:50 PM |
| Left site: | 3:30 PM |
| Site Conditions: | Slightly Damp |
| Weather: | 65°, Raining |
| | _ |

| Transmitted by: | | | |
|-----------------|------|----------|--|
| \boxtimes | Mail | | |
| | Hand | ☐ Other: | |
| | Fax | | |

Comments:

Graves Engineering, Inc. (GEI) was on-site to observe construction of the road's drainage/stormwater management system. This site visit was conducted throughout the entire site. I observed the following:

General Site:

- I spoke with John Walsh, who informed me no work was occurring on site today,
- The uppermost portion of the slope between stations 8+00 and 9+00 needs to be reseeded.
- The area with jute matting between stations 8+00 and 9+00 was beginning to experience grass growth.
- The contractor was moving earth material and hydroseeding slopes on the lots between stations 32+00 and 42+00.

Stormwater Management Areas:

- Stormwater Management Area (SWMA) #1 was experiencing sparse grass growth.
- The jute matting near Forebay 2B in SWMA #2 was well-maintained.
- Grass growth had not yet occurred in SWMA #2 and SWMA #3 near the emergency spillways.

Based upon visual observations only, the work observed today appeared to be consistent with the approved plans.

Action to be Taken:

Client will be notified of this site visit by way of this report.

Copies:

cc: John Walsh; Walsh Contracting Corp. Matthew Piekarski; The Kraft Group, LLC

Photos:

The following photos were taken during today's site visit.



Photo 1: The contractor was performing utility work in Providence Road.



Photo 2: The uppermost portion of the slope between stations 8+00 and 9+00 needs to be reseeded.



Photo 3: The area with jute matting between stations 8+00 and 9+00 was beginning to experience grass growth.