

Site Visit Report



100 Grove Street
Worcester, MA 01605
T 508-856-0321
F 508-856-0357
gravesengineering.com

Date:	April 13, 2023	Prepared By:	Olivia Caton
Client:	Sutton Planning Board	Arrived on site:	10:30 AM
Project:	Unified Parkway	Left site:	11:00 AM
Contractor:	Walsh Contracting Corp.	Site Conditions:	Dry
Contractor Contact:	John Walsh	Weather:	77°, Clear

Transmitted by:

<input checked="" type="checkbox"/> Mail	<input checked="" type="checkbox"/> E-mail
<input type="checkbox"/> Hand	<input type="checkbox"/> Other:
<input type="checkbox"/> Fax	

Comments:

Graves Engineering, Inc. (GEI) was on-site to observe construction of the road's drainage/stormwater management system. This site visit was conducted throughout the entire site. I observed the following:

- The silt fence and stump grindings between the eastern corner of Stormwater Management Area (SWMA) #1 and the property line were well-maintained.
- The jute matting between stations 8+00 and 9+00, as well as at the northern corner of SWMA #2, was in good condition.
- SWMAs #1 and #2 were dry and experiencing sparse grass growth. SWMA #3 was filled with over two feet of water.
- Gravel had been placed along the construction road between the trailers and subdivision road.
- The contractor was moving material throughout the storage area.

Based upon visual observations only, the work observed today appeared to be consistent with the approved plans.

Action to be Taken:

Client will be notified of this site visit by way of this report.

Copies:

cc: John Walsh; Walsh Contracting Corp.
Matthew Piekarski; The Kraft Group, LLC

Photos:

The following photos were taken during today's site visit.



Photo 1: Gravel was placed along the construction road between the trailers and subdivision road (photo taken through tinted window).



Photo 2: SWMA #2 was experiencing sparse grass growth, and the jute matting in the northern corner was in good condition.



Photo 3: SWMA #3 was filled with over 2 feet of water.