Site Visit Report



100 Grove Street Worcester, MA 01605 T 508-856-0321 F 508-856-0357 gravesengineering.com

Olivia Caton Date: March 13, 2023 Prepared By: Arrived on site: Client: Sutton Planning Board 3:45 PM Project: **Unified Parkway** Left site: 4:15 PM **Contractor:** Walsh Contracting Corp. **Site Conditions:** Slightly Damp **Contractor Contact:** John Walsh Weather: 43°, Raining

| Transmitted by: | | |
|-----------------|------|----------|
| \boxtimes | Mail | |
| | Hand | ☐ Other: |
| | Fax | |

Comments:

Graves Engineering, Inc. (GEI) was on-site to observe construction of the road's drainage/stormwater management system. This site visit was conducted throughout the entire site. I observed the following:

- The silt fence and stump grindings between the eastern corner of Stormwater Management Area (SWMA) #1 and the property line were well-maintained.
- The jute matting between stations 8+00 and 9+00, as well as at the northern corner of SWMA #2, was in good condition.
- Three-quarter-inch crushed stone was stockpiled in the storage area as well as outside the right-of-way between stations 13+00 and 19+00.

Based upon visual observations only, the work observed today appeared to be consistent with the approved plans.

Action to be Taken:

Client will be notified of this site visit by way of this report.

Copies:

cc: John Walsh; Walsh Contracting Corp. Matthew Piekarski; The Kraft Group, LLC

Photos:

The following photos were taken during today's site visit.



Photo 1: The silt fence and stump grindings between the eastern corner of Stormwater Management Area (SWMA) #1 and the property line were well-maintained.



Photo 2: Three-quarter-inch crushed stone was stockpiled in the storage area and outside the right-of-way.