

Site Visit Report



100 Grove Street
Worcester, MA 01605
T 508-856-0321
F 508-856-0357
gravesengineering.com

Date: July 26, 2023
Client: Sutton Planning Board
Project: Unified Parkway
Contractor: Walsh Contracting Corp.
Contractor Contact: John Walsh

Prepared By: Olivia Caton
Arrived on site: 11:10 AM
Left site: 11:45 AM
Site Conditions: Dry/Slightly Damp
Weather: 78°, Hazy

Transmitted by:

<input checked="" type="checkbox"/> Mail	<input checked="" type="checkbox"/> E-mail
<input type="checkbox"/> Hand	<input type="checkbox"/> Other:
<input type="checkbox"/> Fax	

Comments:

Graves Engineering, Inc. (GEI) was on-site to observe construction of the road and the road's drainage/stormwater management system. This site visit was conducted throughout the entire site. I observed the following:

- Due to recent rainfall events, several large puddles had formed along the access path near the storage area.
- Stormwater Management Area (SWMA) #1 was experiencing well-established grass growth.
- The slopes along SWMA #2 were experiencing well-established grass growth. No additional grass growth appeared to have occurred along the bottom of the management area since my last site visit on July 7, 2023.
- SWMA #3 was experiencing well-established grass growth along the northern slopes, western slope, and lower portion of the eastern slope. The southeastern slope was experiencing approximately 60% grass growth. The southwestern slope was experiencing approximately 20% grass growth and needs to be reseeded and/or augmented to encourage additional grass growth.
- Sediment had accumulated in Flared End Section (FES) 301. An erosion rill had caused additional sediment buildup in this portion of SWMA #3. The erosion rill needs to be repaired and the sediment cleaned out.
- SWMAs #1 and #2 were dry. Water had pooled in SWMA #3 to approximately one foot deep.
- The contractor was installing electrical conduit pipe at approximately station 52+50.

Based upon visual observations only, the work observed today appeared to be consistent with the approved plans.

Action to be Taken:

Client will be notified of this site visit by way of this report.

Copies:

cc: John Walsh; Walsh Contracting Corp.
Matthew Piekarski; The Kraft Group, LLC

Photos:

The following photos were taken during today's site visit.



Photo 1: Sediment had accumulated in FES-301 and needs to be cleaned out.



Photo 3: The contractor installing electrical conduit pipe at approximately station 52+50.