

Site Visit Report



100 Grove Street
Worcester, MA 01605
T 508-856-0321
F 508-856-0357
gravesengineering.com

Date:	February 14, 2023	Prepared By:	Olivia Caton
Client:	Sutton Planning Board	Arrived on site:	12:00 PM
Project:	Unified Parkway Lots 2 and 3	Left site:	12:30 PM
Contractor:	Walsh Contracting Corp.	Site Conditions:	Dry
Contractor Contact:	John Walsh	Weather:	45°, Mostly Sunny

Transmitted by:

<input checked="" type="checkbox"/> Mail	<input checked="" type="checkbox"/> E-mail
<input type="checkbox"/> Hand	<input type="checkbox"/> Other:
<input type="checkbox"/> Fax	

Comments:

Graves Engineering, Inc. (GEI) was on-site to observe installation of the drainage system. This site visit was conducted throughout the entire site. I observed the following:

- The contractor continued installing the frame of Building 3. Additional construction had been completed on the foundation.
- Earth material had been excavated from Lot 2.
- Sewer Manhole (SMH) 110 had been installed and backfilled until only the top of its cover was visible.
- The contractor was excavating earth material near the locations of Drain Manhole (DMH) 603 and DMH 703.

Based upon visual observations only, the work observed today appeared to be consistent with the approved plans.

Action to be Taken:

Client will be notified of this site visit by way of this report.

Copies:

cc: John Walsh; Walsh Contracting Corp.
Matthew Piekarski; The Kraft Group, LLC

Photos:

The following photos were taken during today's site visit.



Photo 1: The contractor installing the frame of Building 3.



Photo 2: Additional earth material had been excavated from Lot 2.