

Site Visit Report



100 Grove Street
Worcester, MA 01605
T 508-856-0321
F 508-856-0357
gravesengineering.com

| | | | |
|----------------------------|------------------------------|-------------------------|---------------|
| Date: | November 11, 2022 | Prepared By: | Olivia Caton |
| Client: | Sutton Planning Board | Arrived on site: | 3:30 PM |
| Project: | Unified Parkway Lots 2 and 3 | Left site: | 4:00 PM |
| Contractor: | Walsh Contracting Corp. | Site Conditions: | Slightly Damp |
| Contractor Contact: | John Walsh | Weather: | 65°, Raining |

Transmitted by:

| | |
|--|--|
| <input checked="" type="checkbox"/> Mail | <input checked="" type="checkbox"/> E-mail |
| <input type="checkbox"/> Hand | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Fax | |

Comments:

Graves Engineering, Inc. (GEI) was on-site to observe general site conditions. This site visit was conducted throughout the entire site. I observed the following:

- The location of Building 3 had been compacted. A series of square spaces in this space had been cleared, and a portion of them were covered in what appears to be gravel pads for the building columns.
- Gravel pads had been placed for what appears to be the foundation of Building 3.
- The location of the driveway leading to the western trailer parking of Building 2 and a portion of the location of the trailer parking had been compacted.
- Large portions of excess earth material had been removed throughout the site. Some earth material and organic material remained.

Based upon visual observations only, the work observed today appeared to be consistent with the approved plans.

Action to be Taken:

Client will be notified of this site visit by way of this report.

Copies:

cc: John Walsh; Walsh Contracting Corp.
Matthew Piekarski; The Kraft Group, LLC

Photos:

The following photos were taken during today's site visit.



Photo 1: Gravel pads for what appears to be the columns of Building 3.



Photo 2: Gravel pads for what appears to be the foundation of Building 3.



Photo 3: Large amounts of earth material had been removed, with some earth and organic material remaining.