

Site Visit Report



100 Grove Street
Worcester, MA 01605
T 508-856-0321
F 508-856-0357
gravesengineering.com

Date: March 13, 2023
Client: Sutton Planning Board
Project: Unified Parkway Lots 2 and 3
Contractor: Walsh Contracting Corp.
Contractor Contact: John Walsh

Prepared By: Olivia Caton
Arrived on site: 3:15 PM
Left site: 3:45 PM
Site Conditions: Slightly Damp
Weather: 43°, Raining

Transmitted by:

<input checked="" type="checkbox"/> Mail	<input checked="" type="checkbox"/> E-mail
<input type="checkbox"/> Hand	<input type="checkbox"/> Other:
<input type="checkbox"/> Fax	

Comments:

Graves Engineering, Inc. (GEI) was on-site to observe installation of the drainage system. This site visit was conducted throughout the entire site. I observed the following:

- The contractor continued installing the frame of Building 3.
- Gravel had been placed from the entrance to Lot 3 near the contractor trailers to near the edge of Building 3.
- Additional earth material had been placed at the location of the southern parking lot/southern end of Building 2.
- Additional earth material on the southern side of Lot 3, near the locations of Drain Manhole (DMH) 603 and DMH 703, had been excavated.
- The locations of drainage structures had been marked with stakes throughout Lot 3.

Based upon visual observations only, the work observed today appeared to be consistent with the approved plans.

Action to be Taken:

Client will be notified of this site visit by way of this report.

Copies:

cc: John Walsh; Walsh Contracting Corp.
Matthew Piekarski; The Kraft Group, LLC

Photos:

The following photos were taken during today's site visit.



Photo 1: The locations of drainage structures had been staked throughout the site (WQU 705 shown).



Photo 2: Construction continued on the frame of Building 3.