

# Site Visit Report



100 Grove Street  
Worcester, MA 01605  
T 508-856-0321  
F 508-856-0357  
gravesengineering.com

**Date:** December 20, 2022  
**Client:** Sutton Planning Board  
**Project:** Unified Parkway  
**Contractor:** Walsh Contracting Corp.  
**Contractor Contact:** John Walsh

**Prepared By:** Olivia Caton  
**Arrived on site:** 10:40 AM  
**Left site:** 11:15 AM  
**Site Conditions:** Slightly Damp  
**Weather:** 34°, Clear

## Transmitted by:

<input checked="" type="checkbox"/> Mail	<input checked="" type="checkbox"/> E-mail
<input type="checkbox"/> Hand	<input type="checkbox"/> Other:
<input type="checkbox"/> Fax	

## Comments:

Graves Engineering, Inc. (GEI) was on-site to observe construction of the road's drainage/stormwater management system. This site visit was conducted throughout the entire site. I observed the following:

- The contractor was backfilling the electrical utilities, as well as placing earth material outside the right-of-way at station 5+00.
- The slope outside the right-of-way between stations 5+00 and 7+00 had been graded.
- Additional fill material had been placed to fill the temporary construction path between stations 0+00 and 5+00.
- The contractor was placing fill material in one-foot lifts along the roadway at approximately station 53+00.
- The contractor was moving earth material throughout the site.

Based upon visual observations only, the work observed today appeared to be consistent with the approved plans.

## Action to be Taken:

Client will be notified of this site visit by way of this report.

## Copies:

cc: John Walsh; Walsh Contracting Corp.  
Matthew Piekarski; The Kraft Group, LLC

## Photos:

The following photos were taken during today's site visit.



**Photo 1:** The contractor backfilling the electrical utilities as well as placing earth material outside the right-of-way.



**Photo 2:** The slope outside the right-of-way between stations 5+00 and 7+00 had been graded.