

Site Visit Report



100 Grove Street
Worcester, MA 01605
T 508-856-0321
F 508-856-0357
gravesengineering.com

Date: February 24, 2023
Client: Sutton Planning Board
Project: Unified Parkway
Contractor: Walsh Contracting Corp.
Contractor Contact: John Walsh

Prepared By: Olivia Caton
Arrived on site: 11:30 AM
Left site: 12:00 PM
Site Conditions: Snowy
Weather: 32°, Partly Cloudy

Transmitted by:

<input checked="" type="checkbox"/> Mail	<input checked="" type="checkbox"/> E-mail
<input type="checkbox"/> Hand	<input type="checkbox"/> Other:
<input type="checkbox"/> Fax	

Comments:

Graves Engineering, Inc. (GEI) was on-site to observe construction of the road's drainage/stormwater management system. This site visit was conducted throughout the entire site. I observed the following:

- The silt fence and stump grindings between the eastern corner of Stormwater Management Area (SWMA) #1 and the property line were well-maintained.
- The previously installed gas utility pipe between stations 51+00 and 53+75 had been backfilled and was no longer visible.
- The contractor was moving materials throughout the site.

Based upon visual observations only, the work observed today appeared to be consistent with the approved plans.

Action to be Taken:

Client will be notified of this site visit by way of this report.

Copies:

cc: John Walsh; Walsh Contracting Corp.
Matthew Piekarski; The Kraft Group, LLC

Photos:

The following photos were taken during today's site visit.



Photo 1: The silt fence and stump grindings between the eastern corner of Stormwater Management Area (SWMA) #1 and the property line were well-maintained.



Photo 2: The previously installed gas utility pipe between stations 51+00 and 53+75 had been backfilled.